


Haverford Free Library  
Existing Conditions Photographs



P-1  
Broken water line at cooling  
tower




P-2  
Poor flashing at clerestory



P-3  
Broken drain screen


Haverford Free Library  
Existing Conditions Photographs



P-4  
Broken drain screen, poor  
flashing




P-5  
Ridging and bubbling of built-up  
roof



P-6  
Downspout dumping directly onto  
roof

Haverford Free Library  
Existing Conditions Photographs



P-7  
Debris on roof




P-8  
Debris blocking  
downspout/drain



P-9  
Computer lab rooftop unit




Haverford Free Library  
Existing Conditions Photographs



P-10  
Exhaust fan.



P-11  
Downspout emptying on roof



P-12  
Debris on roof (blocking drain)


Haverford Free Library  
Existing Conditions Photographs



P-13  
Ice on roof indicates ponding  
water




P-14  
Roof repair at cooling tower wall




P-15  
Cooling tower.

Haverford Free Library  
Existing Conditions Photographs



P-16  
Roof repair and ridging of built-up roof




P-17  
Cover off of electrical panel  
(dangerous condition)



P-18  
Open ductwork



Haverford Free Library  
Existing Conditions Photographs



P-19  
Fatigued vibration dampers




P-20  
Non-accessible toilet and sink




P-21  
Obsolete kitchen

Haverford Free Library  
Existing Conditions Photographs



P-22  
Moss and ice indicative of  
ponding water



P-23  
Unshielded cable




P-24  
Electrical box coming off wall




Haverford Free Library  
Existing Conditions Photographs



P-25  
Smoke detectors




P-26  
Life safety items including exit  
sign, battery pack, pull station and  
fire extinguisher



P-27  
Non-accessible toilet

Haverford Free Library  
Existing Conditions Photographs



P-28  
Non-accessible sink



P-29  
Water damage at clerestory  
flashing




P-30  
Water damage at clerestory roof

Haverford Free Library  
Existing Conditions Photographs



P-31  
Water damage at clerestory  
flashing




P-32  
Water damage at clerestory  
flashing



P-33  
Poor circulation and use of  
space




Haverford Free Library  
Existing Conditions Photographs



P-34  
Life safety elements



P-35  
Obsolete and inefficient lighting



P-36  
Failing sealant

Haverford Free Library  
Existing Conditions Photographs



P-37  
Failed sealant




P-38  
Corroded doorframe



P-39  
Cracked sidewalk

Haverford Free Library  
Existing Conditions Photographs



P-40  
Corroding metal paneling




P-41  
Cracking sidewalk




P-42  
Failing panel joints



Haverford Free Library  
Existing Conditions Photographs



P-43  
Failing sealant




P-44  
Failing panel joints




P-45  
Damaged and delaminating  
panels


Haverford Free Library  
Existing Conditions Photographs



P-46  
Failing ceramic tile




P-47  
New lighting added to replace  
original




P-48  
Poor space planning and  
utilization


Haverford Free Library  
Existing Conditions Photographs



P-49  
Grille kicked in and damaged fin-tubes



P-50  
Damaged thermostat



P-51  
Tape over air supply



## Haverford Free Library Existing Conditions Photographs



P-52  
Cluttered appearance and poor  
circulation




P-53  
Poor lighting and signage




P-54  
Poor lighting and inefficient use  
of space


Haverford Free Library  
Existing Conditions Photographs



P-55  
Water damage under stair tower  
roof




P-56  
Open cable tray on computer table




P-57  
Computer table wiring  
connections

Haverford Free Library  
Existing Conditions Photographs



P-58  
Exposed foundation drainage




P-59  
Northwestern sump



P-60  
Typical VAV box



Haverford Free Library  
Existing Conditions Photographs



P-61  
Open Junction box and  
unshielded cable




P-62  
Temporary duct extension




P-63  
Concrete structure at Bank  
basement


Haverford Free Library  
Existing Conditions Photographs



P-64  
Water damage under front stair  
(reinforcing bars)




P-65  
Water damage at bottom of east  
stair tower



P-66  
Temporary pipe support

Haverford Free Library  
Existing Conditions Photographs




P-67  
Water damage at basement

P-68  
Water damage at electrical  
service boxes in SW corner of  
mechanical room



Haverford Free Library  
Existing Conditions Photographs



P-68  
No enclosure to elevator  
machine



P-69  
Water damage to SW corner of  
mechanical room